

Characteristics:

Solution™ Sub Block is a printable and cuttable material and especially developed for sublimated polyester garments. Once CAD-COLOR® Solution™ Sub Block is heat applied, it provides a barrier eliminating dye migration. Due to the barrier only limited stretchable.

Application Information:

100% cotton, cotton blends, 100% polyester, polyester blends

Printable Information:

Solvent and Eco Solvent inks

Availability:

50 cm width, 20 m length

Washability:

up to 40°C

Wash and iron garment inside out

Processing Instructions:

Do not mirror image. When printing, please pay attention that the paper faces down and ensure that the correct printing parameters are used and adjusted accordingly. The imprinted material has to repose for 4 hours if the cutting line lies inside of the motive. Remove excess material and affix the application tape CAD-COLOR® Magic Mask® onto the material. In order to avoid bubbles between the motive and the carrier, we recommend to use a squeegee. Remove image from carrier, place on garment and heat apply as listed below:

Printing Parameters:

Always pre-heat garment before starting the heat application for 5 -10 seconds in order to remove possible moisture and / or chemical residue.

Temperature: 155°C
Time: 10 seconds
Pressure: medium
Remove Magic Mask®: warm / cold

Accessories:

Teflon® cover sheet, Grip cover sheet, EZ Weeder™, CAD-COLOR® Magic Mask®